

Labor and Materials

Copper } Connection, 3/4	\$ 3.20
Lead } Connection, 3/4	
Curb } Cock	
} Valve	
} T.S. & V. } 3/4 in.	\$ 1.00
Service Box } Short 3 1/2 x 4 1/2	
Old returned } Long 4 1/2 x 5 1/2	
} Buff. or Rdway	\$ 1.40
18 Ft. 3/4 in. } Copper	
} Galv. Iron	
} Cast Iron	
} Pipe at	\$ 2.80
Nipples.....in. at	\$
Bushings.....to.....in. at	\$
Red'g } Couplings.....to.....in. at	\$
Inc'g }	
Union.....in. at	\$
Meter.....in. at	\$
Lbs. Br. Stone at	\$
Lbs. Sand at	\$
Cement at	\$
Paving Brick } (Mack	
} Red	
} Asphalt	
} at	\$
Lead Joints at	\$
Leadite Joints at	\$
Hrs. Foreman at 6.35	\$ 1.38
Hrs. Common Labor at 1.50	\$ 2.00
Hrs. Common Labor at 4.06	\$ 4.06
Hrs. Mason at	\$
Hrs. Mason's Helper at	\$
Hrs. Compressor at	\$
Compensation Ins.	\$ 28
Trucking	\$ 1.00
Builders' Use of Water	\$
Total	\$ 22.18

26-117 ~~857700~~

Labor and Material Report Aug 19 19 20

109 109AB

● Curb Box

RAZED

Main Elev. of Main at tap 6.11

Gate at ● Gate at ●

● Curb Box