

### Labor and Materials

1	Copper } Connection		\$ 3.20
	Lead } Connection		
1	Curb { Cock } { Valve } { T.S. & V. }	3/4 in.	\$ 1.00
1	Service Box { Short 3 1/2 x 4 1/2 } Old returned { Long 4 1/2 x 5 1/2 } { Butt or Rdway }		\$ 1.30
9 1/2	Ft. 3/4 in. { Copper } { Galv. Iron } { Cast Iron }	Pipe at	\$ 7.92
	Nipples	in. at	\$
1	Bushings	3/4 to 3/4 in. at	\$ .08
1	Red } Taps } Couplings	3/4 to 3/4 in. at	\$ .15
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone	at	\$
	Lbs. Sand	at	\$
	Bags Cement	at	\$
	Paving Brick { Mack } { Red } { Asphalt }	at	\$
	Lead Joints	at	\$
	Leadite Joints	at	\$
4	Hrs. Foreman	at 6.25	\$ 25.00
11	Hrs. Common Labor	at 5.00	\$ 55.00
1.20	Hrs. Common Labor	at 4.00	\$ 4.80
	Hrs. Mason	at	\$
	Hrs. Mason's Helper	at	\$
	Hrs. Compressor	at	\$
	Compensation Ins.	at	\$ .33
	Trucking	at	\$ 1.00
	Builders' Use of Water	at	\$
Total			\$ 27.85

26-114 #110

Labor and Material Report Aug 16 1926

88 Broad Street

#110 See below

House to be RAZED

18'0" Curb Box

35'-3" Elev. of Main at tap 5

6 Main Gate at Gate at

Shut off at 16' at curb 11/20/22

26

From House