

**Labor and Materials**

1	Copper } Connection.....	7.20
	Lead } .....	
1	Curb { Cock } .....	1.00
	{ Valve } .....	
	{ T.S. & V. } .....	
1	Service Box { Short 3' x 4' } .....	1.30
	{ Long 4' x 5' } .....	
	{ Buff. or Rdway } .....	
113	Ft. { Copper } Pipe at .....	9.46
	{ Galv. Iron } .....	
	{ Cast Iron } .....	
	Nipples..... in. at.....	\$
	Bushings..... to..... in. at.....	\$
	Red'g } Couplings..... to..... in. at.....	\$
	Inc'g } .....	
	Union..... in. at.....	\$
	Meter..... in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement at.....	\$
	Paving Brick { Mack } at.....	\$
	{ Red } .....	
	{ Asphalt } .....	
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
2	Hrs. Foreman at.....	1.25
15	Hrs. Common Labor at.....	6.09
	Hrs. Common Labor at.....	\$
	Hrs. Mason at.....	\$
	Hrs. Mason's Helper at.....	\$
	Hrs. Compressor at.....	\$
	Compensation Ins.....	1.19
1.00	Trucking.....	1.00
2.00	Builders' Use of Water.....	\$
	<b>Total</b>	<b>23.49</b>

112  
Labor and Material Report *July 20* 19*25*

90' Broad



**RAZED**

Gate at ●

● Gate at

● Curb Box