

Labor and Materials

1	Copper } Connection	3/4	\$ 3.20	
1	Curb } Cock Valve	3/4 in.	\$ 1.00	
		P. S. & V.		
1	Service Box } Short 3 1/2 x 4 1/2		\$ 1.30	
	Old returned } Long 4 1/2 x 5 1/2			
		Bull. or Rdway		
1.2	Ft. } 1/2 in. } Copper		\$ 2.64	
		Galv. Iron		
		Cast Iron		
	Nipples	in. at	\$	
	Bushings	to.....in. at	\$	
	Red'g } Couplings	to.....in. at	\$	
	Inc'g }			
	Union	in. at	\$	
	Meter	in. at	\$	
	Lbs. Br. Stone	at	\$	
	Lbs. Sand	at	\$	
	Bags Cement	at	\$	
	Paving Brick } Mack	} at	\$	
				Red
				Asphalt
	Lead Joints	at	\$	
	Leadite Joints	at	\$	
2	Hrs. Foreman	at 6.25	\$ 1.25	
8	Hrs. Common Labor	at 50	\$ 3.50	
8	Hrs. Common Labor	at 40 3/8	\$ 3.25	
	Hrs. Mason	at	\$	
	Hrs. Mason's Helper	at	\$	
	Hrs. Compressor	at	\$	
	Compensation Ins.		\$ 2.2	
	Trucking		\$ 1.00	
	Builders' Use of Water		\$	
Total			\$ 17.36	

26-65

Labor and Material Report

19 26

93 Bona L & K



Revised
1985

● Curb Box

6' Main

Elev. of
Main at tap

Gate at ●

● Gate at

● Curb Box