

LABOR AND MATERIALS

Copper } Connection \_\_\_\_\_ \$ \_\_\_\_\_  
 Lead }  
 Curb } Cock } \_\_\_\_\_ in. \$ \_\_\_\_\_  
       } Valve }  
       } T. S. & V. }  
 Service box { Short 3 1/2 x 4 1/2 }  
 Old returned { Long 4 1/2 x 5 1/2 }  
                   { Buff or Rdway } \_\_\_\_\_ \$ \_\_\_\_\_  
 10 Ft. 1 in. { Copper } Pipe at \_\_\_\_\_ \$ \_\_\_\_\_  
                   { G. I. }  
                   { C. I. }  
 Nipples \_\_\_\_\_ in. at \_\_\_\_\_ \$ \_\_\_\_\_  
 Bushings \_\_\_\_\_ to \_\_\_\_\_ in. at \_\_\_\_\_ \$ \_\_\_\_\_  
 Red'g }  
 Inc'g } Coupl'gs \_\_\_\_\_ to \_\_\_\_\_ in. at \_\_\_\_\_ \$ \_\_\_\_\_  
 Union \_\_\_\_\_ in. at \_\_\_\_\_ \$ \_\_\_\_\_  
 Meter \_\_\_\_\_ in. at \_\_\_\_\_ \$ \_\_\_\_\_  
 Lead Joints at \_\_\_\_\_ \$ \_\_\_\_\_  
 Compound Joints at \_\_\_\_\_ \$ \_\_\_\_\_  
 Maintenance Foreman \_\_\_\_\_ \$ \_\_\_\_\_  
 Hrs. Water Maint. Man—1 at \_\_\_\_\_ \$ \_\_\_\_\_  
 Hrs. Water Maint. Man—2 at \_\_\_\_\_ \$ \_\_\_\_\_  
 Hrs. Garage Foreman \_\_\_\_\_ at \_\_\_\_\_ \$ \_\_\_\_\_  
 Hrs. Labor— \_\_\_\_\_ at \_\_\_\_\_ \$ \_\_\_\_\_  
 Hrs. Compressor at \_\_\_\_\_ \$ \_\_\_\_\_  
 Compensation Ins. at \$ \_\_\_\_\_ per C \_\_\_\_\_ \$ \_\_\_\_\_  
 Trucking \_\_\_\_\_ \$ \_\_\_\_\_  
 Pav't Patch \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 O'head \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_

St. Broad  
 Pt. 118  
 Ave. No. 130

Hudson & Broad  
 Name of Owner  
STEWARTS

Labor and Mat'l. Report \_\_\_\_\_ 19 81

Broad St.  
 Hudson Ave.  
 Building OR  
 Stewart's  
 28'3"  
 16'1"  
 Curb Box  
 MEASUREMENTS COMES OFF OF SIDE OF BUILDING ON HUDSON AVE.

Main \_\_\_\_\_ Elev. of \_\_\_\_\_  
 Main at tap \_\_\_\_\_  
 Gate at • \_\_\_\_\_ Gate at • \_\_\_\_\_  
 TAX ID # 309.35-2-4  
 • Curb Box

LSM-5C-6-1-67