

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$
1	Lead	Cock		\$
1	Curb	Valve	3/4 in. original	\$
		T. S. & V.		\$
1	Service box	Short 3 1/2 x 4 1/2		\$
	Old returned	Long 4 1/2 x 5 1/2		\$
		Buff or Rdway		\$
22	Ft.	Copper	3/4 in.	Pipe at \$
		C.I.		\$
		C.I.		\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g	Coupl'gs	to in. at	\$
	Inc'g			\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins. at \$	per C		\$
	Trucking			\$
	Pav't Patch			\$
	TAP BY PUYVIS & CO			\$
	Dec-17-1976			\$
	O'head			\$

Home

BROAD

St. Rear
Pl:
Ave. No. 123

Name of Owner _____

Labor and Mat'l. Report *Dec 17* 19 *76*

#123A B **RAZED**

LAWYERS OFFICE →

#123 C **RAZED**

19'-9" 21'-8"

● Curb Box

6" Main Elev. of Main at tap 6"

Gate at ● ● Gate at

● Curb Box

LSM-5C-6-1-67