

Labor and Materials

Copper	{	Connection.....	\$
Lead			
Curb	{	Cock Valve	in \$
		T. S. & V.	
Service Box	{	Short 3½ x 4½	\$
Old returned		Long 4½ x 5½	
		Buff. or Rdway	
Ft.in.	{	Copper	Pipe at \$
		Galv Iron	
		Cast Iron	
Nipples	in. at		\$
Bushings	to	in. at	\$
Red'g	{	Couplings.....to	in. at \$
Inc'g			
Union	in. at		\$
Meter	in. at		\$
Lead Joints	at		\$
Leadite Joints	at		\$
Hrs. Foreman	at		\$
Hrs. Chauffeur	at		\$
Hrs. Tapper	at		\$
Hrs. Labor	at		\$
Hrs. Labor	at		\$
Hrs. Compressor	at		\$
Compensation Ins.			\$
Trucking			\$
Builders Use of Water			\$
			\$
			\$
			\$
			\$
			\$
			\$
			\$

St. 17
 Pl. 17
 Ave. No. 121

Name of Owner
Jas. Small

Labor and Mat'l. Report 11/2/16 19

1477-13

RAZED

1998

37.6 34.4

● Curb Box

6
 Main

Elev. of
 Main at tap.....

Gate at ●

● Gate at

● Curb Box