

# LABOR AND MATERIALS

Copper } Connection ..... \$ .....  
 Lead }  
 Curb { Clock Valve } ..... in. \$ .....  
       { T. S. & V. }  
 Service box { Short 3 1/2 X 4 3/4 } ..... \$ .....  
 Old returned { Long 4 1/2 X 5 3/4 }  
               { Buff or Rdway }  
 Ft. .... in. { Copper } *Gal* Pipe at \$ .....  
                   { Galv. Iron }  
                   { Cast Iron }  
 Nipples ..... in. at \$ .....  
 Bushings ..... to ..... in. at \$ .....  
 Red'g } Couplings ..... to ..... in. at \$ .....  
 Inc'g }  
 Union ..... in. at \$ .....  
 Meter ..... in. at \$ .....  
 Lead Joints at \$ .....  
 Compound Joints at \$ .....  
 Hrs. Foreman at \$ .....  
 Hrs. Chauffeur at \$ .....  
 Hrs. Tapper at \$ .....  
 Hrs. Labor at \$ .....  
 Hrs. Labor at \$ .....  
 Hrs. Compressor at \$ .....  
 Compensation Ins. \$ .....  
 Trucking \$ .....  
 Builders Use of Water \$ .....  
*Materials by Manufacturer + 6.00* \$ .....  
 \$ .....  
 \$ .....

St. *168*

Pl. *132*

Ave. No. *132*

*Broad*

Name of Owner \_\_\_\_\_

Labor and Mat'l. Report *Dec 11* 19*40*

● Curb Box

---

Main Elev. of Main at tap.....

Gate at ● ● Gate at

● Curb Box

L9M-5C-6-1-48