

**Labor and Materials**

1	Copper } Connection	?	\$ 2.60
	Lead }		
1	Curb } Cock	4	\$ 2.30
	Waive }	?	
	S.S. & V. }	?	
1	Service Box } Short 3 1/2 x 1 1/2		\$ 1.40
	Old returned } Long 4 1/2 x 3 1/2		
	Buff. or Rdway }		
2.4	Ft. in. } Copper	?	\$ 6.26
	Galv. Iron }	?	
	Cast Iron }	?	
	Pipe at		
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Couplings	to in. at	\$
	Inc'g }		
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone at		\$
	Lbs. Sand at		\$
	Bags Cement at		\$
	Paving Brick } Mack	} at	\$
	Red		
	Asphalt		
	Lead Joints at		\$
	Leadite Joints at		\$
4	Hrs. Foreman at		\$ 2.50
3	Hrs. Common Labor at		\$ 1.50
13	Hrs. Common Labor at		\$ 5.28
	Hrs. Mason at		\$
	Hrs. Mason's Helper at		\$
	Hrs. Compressor at		\$
	Compensation Ins.		\$ .25
	Trucking		\$ 1.00
	Builders' Use of Water	Patch	\$ 5.00

Total \$ 28.19

29-64

**Labor and Material Report**

1929

144 Broad St.  
139



RAZED

6 Main

Elev of Main at tap 1 1/2

Gate at ●

● Gate at

● Curb Box