

Labor and Materials

1	Copper } Connection	35	\$ 3.20
	Lead }		
1	Curb } Cock	1	\$ 1.00
	Valve }		
	T. S. & V. }		
	Service Box } Short 3 1/2 x 4 1/2		\$ 1.30
	Old returned } Long 4 1/2 x 5 1/2		
		Buff. or Rdway	
39	Pt. 3/4 in. } Copper		\$ 8.58
		Galv. Iron	
		Cast Iron	
	Nipples	in. at	\$
	Bushings	to	\$.08
1	Red'g } Couplings	2	\$ 1.5
	Inc'g }	to	
	Union	in. at	\$
	Meter	in. at	\$
	Lbs. Br. Stone at		\$
	Lbs. Sand at		\$
	Bags Cement at		\$
	Paving Brick } Mack		\$
		Red	
		Asphalt	
	Lead Joints at		\$
2	Leadite Joints at		\$
4	Hrs. Foreman at	62.5	\$ 2.50
20	Hrs. Common Labor at	50	\$ 10.00
8	Hrs. Common Labor at	40 1/4	\$ 3.25
	Hrs. Mason at		\$
	Hrs. Mason's Helper at		\$
	Hrs. Compressor at		\$
	Compensation Ins.		\$ 4.2
	Trucking		\$ 1.00
	Builders' Use of Water		\$
Total			\$ 31.48

26-38

Labor and Material Report June 3, 1921

144, 146, 148, 150, 152



RAZED

Main Eley. of Main at tap

Gate at Gate at

Curb Box