

Labor and Materials

Copper	Connection.....	3	\$ 1.50
Lead		3	
Curb	{ Cock Valve }in	7	\$ 1.70
	{ T.S.&V. }		
Service Box	{ Short 3 1/2 x 4 1/2 }		\$ 1.44
Old returned	{ Long 4 1/2 x 5 1/2 }		
	{ Bell on Edway }		
9 Ft.	2 in. { Copper } Pipe at		\$ 1.71
	{ Galv. Iron }		
	{ Cast Iron }		
Nipplesin. at		\$
Bushingstoin. at		\$
Red'g Inc'g	{ Couplings.....to.....in. at		\$
Unionin. at		\$
Meterin. at		\$
Lbs. Br. Stone	at		\$
Lbs. Sand	at		\$
Bags Cement	at		\$
Paving Brick	{ Mack } at		\$
	{ Red }		
	{ Asphalt }		
Lead Joints	at		\$
Leadite Joints	at		\$
7 Hrs. Foreman	at	67.18	\$ 1.35
4 Hrs. Common Labor	at	25.74	\$.82
8 1/2 Hrs. Common Labor	at	15.74	\$.85
2 1/4 Hrs. Mason	at	45	\$.34
Hrs. Masons Helper	at		\$
Hrs. Compressor	at		\$
Compensation Ins			\$ 4.10
Trucking			\$ 0.75
Builders Use of Water			\$
Total \$			9.85

61 34 193 July 20 19

Labor and Material Report

147 Board St

783



RAZED

6 Main

Elev. of Main at tap 5

Gate at ●

● Gate at

● Curb Box

old shut off at main

Lebowitz

To be changed to Lebowitz