

LABOR AND MATERIALS

1 Copper Lead } Connection $\frac{3}{4}$ \$ 2.80
1 Curb } Clock Valve } $\frac{3}{4}$ in. \$ 3.60
 } T. S. & V. }
1 Service box } Short $3\frac{1}{2}$ X $4\frac{1}{2}$ }
 Old returned } Long $4\frac{1}{2}$ X $5\frac{1}{2}$ }
 } Buff or Rdway } \$ 5.80
25 Ft. $\frac{3}{4}$ in. } Copper Pipe at 35 \$ 8.75
 } Galv. Iron }
 } Cast Iron }

Nipples in. at \$
Bushings to in. at \$
Red'g } Couplings to in. at \$
Inc'g }

Union in. at \$
Meter in. at \$
Lead Joints at \$
Compound Joints at \$

8 Hrs. Foreman at WWM - $9\frac{1}{2}$ \$ 7.40
12 Hrs. Chauffeur at $8\frac{1}{2}$ \$ 9.90
Hrs. Tapper at \$
23 Hrs. Labor at $7\frac{1}{2}$ \$ 16.45
Hrs. Labor at \$
Hrs. Compressor at \$
Compensation Ins. \$ 1.24
Trucking \$ 1.24
Builders Use of Water \$ 6.20
copy Matzinski \$
..... \$
..... \$
..... \$
\$ 62.64

4-47 ✓
Bush
St. Pl. Ave. No. 51
Name of Owner
Lyman Shappy
Labor and Mat'l. Report *Cip' 4* 1947

6 Main Elev. of Main at tap 4
Gate at Gate at
TAX ID # 309.15-8-6
Curb Box

L5M-5C-6-1-45