

LABOR AND MATERIALS

3/4 Copper	} Connection		\$	
Lead				
3/4 Curb	} Cock Valve T.S. & V.	in.	\$	
1 Service box		} Short 3 1/2 x 4 1/2		
Old returned			Long 4 1/2 x 5 1/2	\$
10 Ft. 3/4 in.	} Copper	} Pipe at	\$	
			C.I.	
			\$	
Nipples	in. at		\$	
Bushings	to in. at		\$	
Red'g } Inc'g }	Coupl'gs to in. at		\$	
Union	in. at		\$	
Meter	in. at		\$	
			\$	
Compound Joints	at		\$	
Maintenance Foreman			\$	
Hrs. Water Maint. Man-1	at		\$	
Hrs. Water Maint. Man-2	at		\$	
Hrs. Garage Foreman	at		\$	
Hrs. Labor	at		\$	
Hrs. Compressor	at		\$	
			\$	
Trucking			\$	
Pav't Patch			\$	
			\$	
			\$	
			\$	
			\$	

BYRNE

~~St.~~
~~Pl.~~
Ave. No. 7

Name of Owner

Labor and Mat'l. Report

AUG 1937



23'6" 24'11"

● Curb Box

12" Main

Elev. of Main at tap 52'

Gate at ●

● Gate at

● Curb Box