

LABOR AND MATERIALS

1	Copper } Connection <sup>3/4"</sup>	\$
	Lead }	
1	Curb } Cock <sup>3/4"</sup>	\$
	Valve }	
	T.S. & V. }	
1	Service box { Short 3 1/2 x 4 1/2 }	\$
	Old returned { Long 4 1/2 x 5 1/2 }	
9	Ft. <sup>3/4"</sup> in. { Copper } Pipe at	\$
	{ G.I. }	
	{ C.I. }	
	Nipples in. at	\$
	Bushings to in. at	\$
	Red'g } Inc'g } Coupl'gs to in. at	\$
	Union in. at	\$
	Meter in. at	\$
	Compound Joints at	\$
	Maintenance Foreman	\$
	Hrs. Water Maint. Man—1 at	\$
	Hrs. Water Maint. Man—2 at	\$
	Hrs. Garage Foreman at	\$
	Hrs. Labor at	\$
	Hrs. Compressor at	\$
	Trucking	\$
	Pav't Patch	\$
		\$
		\$
		\$
		\$
		\$

*BYRNE*

St. \_\_\_\_\_  
Pt. \_\_\_\_\_  
Ave. No. *15*

---

Name of Owner \_\_\_\_\_

---

Labor and Mat'l. Report *MAR. 1936*

---

*29 1/2" 27'*

● Curb Box

---

*12"* Main Elev. of Main at tap *4'*

Gate at ● ● Gate at

---

● Curb Box