

LABOR AND MATERIALS

1	Copper	} Connection <sup>3/4</sup>	_____	\$	_____	
	Lead					
1	Curb	} Cock Valve } 1" in.	_____	\$	_____	
			T.S. & V.			
1	Service box	} Short 3 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2 }	_____	\$	_____	
	Old returned					
21'	Ft. 1" in.	} Copper G. I. } Pipe at	_____	\$	_____	
			C. F.			
	Nipples	_____ in. at	_____	\$	_____	
	Bushings	_____ to _____ in. at	_____	\$	_____	
	Red'g	} Coupl'gs. _____ to _____ in. at	_____	\$	_____	
	Inc'g					
	Union	_____ in. at	_____	\$	_____	
	Meter	_____ in. at	_____	\$	_____	
			_____	\$	_____	
	Compound Joints	at	_____	\$	_____	
	Maintenance Foreman		_____	\$	_____	
	Hrs. Water Maint. Man—1	at	_____	\$	_____	
	Hrs. Water Maint. Man—2	at	_____	\$	_____	
	Hrs. Garage Foreman	at	_____	\$	_____	
	Hrs. Labor—	at	_____	\$	_____	
	Hrs. Compressor	at	_____	\$	_____	
			_____	\$	_____	
	Trucking		_____	\$	_____	
	Pav't Patch		_____	\$	_____	
			_____	\$	_____	
			_____	\$	_____	
			_____	\$	_____	
			_____	\$	_____	

BYRNE St. Pt. Ave. No. 16

Name of Owner

Labor and Mat'l. Report SEPT 19 24



3 1/2" 3 1/3"

● Curb Box

12" Main Elev. of Main at tap 4'

Gate at ● Gate at

● Curb Box