

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$
1	Curb	Cock Valve T.S. & V.	1" in.	\$
1	Service box Old returned	Short 3 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2 }		\$
6	Ft. 1" in.	Copper G. I. Pipe at		\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$
				\$

St. _____
 Ph. _____
 Ave. No. 10

CAMERON
 Name of Owner _____
 TAX ID # 302.12-25-6

Labor and Mat'l. Report _____ 19 24



4" Main _____ Elev. of Main at tap 4'
 Gate at • _____ Gate at _____

3/4" LEAD _____
 6' 1" G.I. _____ ● Curb Box