

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$
1	Lead	Cock	3/4 in.	\$
1	Curb	Valve	3/4 in.	\$
		T.S. & V.		
1	Service box	Short 3 1/2 x 4 1/2		
	-Old returned	Long 4 1/2 x 5 1/2		
		Buff. or Rdway		\$
25	Ft. 3/4 in.	Copper	Pipe at	\$
		G.I.		
		G.I.		
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g	Coupl'gs	to in. at	\$
	Inc'g			
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins. at \$	per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap by Gissard			\$
	Coil 6-11/13-56			\$
	O'head			\$

✓

Carleton Ct. Str. No. 7

Name of Owner _____

Labor and Mat'l. Report June 11/13 1956

6" Main Elev. of Main at tap. 5'-8"

Gate at • • Gate at

TAX ID # 309.7-4-14

• Curb Box

LSM-5C-2-5 56