

LABOR AND MATERIALS

1 Copper } Connection 3/4" \$
 Lead }
 1 Curb { Cock } 3/4 in. \$
 Same { Valve }
 T. S. & V. }
 Service Box { Short 3 1/2 x 4 1/2 } \$
 Old returned { Long 4 1/2 x 5 1/2 }
 { Buff. or Rdway }
 21 Ft. 3/4 in. { Copper } Pipe at \$
 { Galv Iron }
 { Cast Iron }
 Nipples in. at \$
 Bushings to in. at \$
 Red'g } Couplings to in. at \$
 Inc'g }
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Leadite Joints at \$
 Hrs. Foreman at \$
 Hrs. Chauffeur at \$
 Hrs. Tapper at \$
 Hrs. Labor at \$
 Hrs. Labor at \$
 Hrs. Compressor at \$
 Compensation Ins. \$
 Trucking \$
 Builders Use of Water \$
 Tap by G. L. S. S. & Co. \$
 6-17-59 \$
 \$
 \$
 \$

✓

St. 16
 Pl. Center
 Ave. No. 14

Name of Owner
Tau Der Voort

Labor and Mat'l. Report June 17 1959

4 galv. Main Elev. of Main at tap 6'

Gate at ● Gate at ●

TAX ID # 303.17-17-3

● Curb Box