

LABOR AND MATERIALS

1	Copper	} Connection	3/4		\$ 2.80
	Lead				
1	Curb	{ Clock Valve	3/4	in.	\$ 3.60
		{ T. S. & V.			
1	Service box	{ Short 3/4 X 4 1/2			\$ 5.80
	Old returned	{ Long 4 1/2 X 5 1/2		Buff or Rdway	
25	Ft.	{ Copper		Pipe at 3/4	\$ 8.75
		{ Galv. Iron			
		{ Cast Iron			
	Nipples in. at			\$
	Bushings to in. at			\$
	Red'g	} Couplings..... to in. at			\$
	Inc'g				
	Union in. at			\$
	Meter in. at			\$
	Lead Joints at				\$
	Compound Joints at				\$
	Hrs. Foreman at				\$
	Hrs. Chauffeur at				\$
	Hrs. Tapper at				\$
	Hrs. Labor at				\$
	Hrs. Labor at				\$
	Hrs. Compressor at				\$
	Compensation Ins.				\$
	Trucking				\$ 1.-
	Builders Use of Water				\$
	Tap by Miller				\$
					\$
					\$
					\$
					\$

103-47

St. Cherry
 Ave. No. 22

Name of Owner Preston

Labor and Mat'l. Report Aug 12 1947

24'8" 17'2"
 ● Curb Box

4 Main Elev. of Main at tap 5-

Gate at ● ● Gate at

● Curb Box

LSM-5C-6-1-45