

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$
1	Curb	Cock Valve T.S. & V.	3/4" in.	\$
Same	Service box	Short 3 1/2 x 4 1/2	} 5x6'	\$
	Old returned	Long 4 1/2 x 5 1/2		
		Buff or Rdway		
2.5	Ft.	3/4 in.	Copper G.I. C.I. } Pipe at	\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Coupl'gs. to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	at \$ per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap by G. L. G. & Co.			\$
	Con. 8-27-59.			\$
	O'head			\$

✓

St. Cherry Ave. No. 65

Name of Owner O'Connor

Labor and Mat'l. Report Aug 27 19 59

4" Main

Elev. of Main at tap 4 1/2'

Gate at •

• Gate at

• Curb Box

19' 10"

35' 2"

• Curb Box

LSM-6C-2-5 56