

LABOR AND MATERIALS

| | | | | | | |
|---|-------------------------|---|------------|--------------|-----|--------------|
| 1 | Copper | } | Connection | <u>3/4"</u> | | \$ |
| | Lead | | | | | |
| 1 | Curb | | Cock Valve | <u>3/4"</u> | in. | \$ |
| | | | T.S. & V. | | | |
| 1 | Service box | | Short | <u>3 1/2</u> | x | <u>4 1/2</u> |
| | Old returned | | Long | <u>4 1/2</u> | x | <u>5 1/2</u> |
| | | | | | | \$ |
| 9 | Ft. | | Copper | | | \$ |
| | <u>3/4"</u> | | G.I. | | | |
| | in. | | G.I. | | | |
| | | | | | | \$ |
| | Nipples | | | | | \$ |
| | Bushings | | | | | \$ |
| | Red'g | | | | | \$ |
| | Inc'g | | | | | \$ |
| | Union | | | | | \$ |
| | Meter | | | | | \$ |
| | | | | | | \$ |
| | Compound Joints | | | | | \$ |
| | Maintenance Foreman | | | | | \$ |
| | Hrs. Water Maint. Man-1 | | | | | \$ |
| | Hrs. Water Maint. Man-2 | | | | | \$ |
| | Hrs. Garage Foreman | | | | | \$ |
| | Hrs. Labor | | | | | \$ |
| | Hrs. Compressor | | | | | \$ |
| | | | | | | \$ |
| | Trucking | | | | | \$ |
| | Pav't Patch | | | | | \$ |
| | | | | | | \$ |
| | | | | | | \$ |
| | | | | | | \$ |
| | | | | | | \$ |

CHERRY St. 78
 Ave. No. 78

Name of Owner

Labor and Mat'l. Report MAY 1932



24'10" 15'2"
 ● Curb Box

4" Main Elev. of Main at tap 5'

Gate at ● Gate at ●

● Curb Box