

LABOR AND MATERIALS

1	Copper Lead	} Connection	^{3/4"}			\$
1	Curb	{ Cock Valve Fr. S. & V. }	^{3/4"}	in.		\$
1	Service Box Old returned	{ Short 3"x4" Long 4"x5" Buffer Rdway }				\$
24	Ft.	^{3/4"} in.	{ Copper Galv Iron Cast Iron }	Pipe at		\$
	Nipples in. at				\$
	Bushings to in. at				\$
	Red'g Inc'g	} Couplings to in. at		\$
	Union in. at				\$
	Meter in. at				\$
	Lead Joints at					\$
	Leadite Joints at					\$
	Hrs. Foreman at					\$
	Hrs. Chauffeur at					\$
	Hrs. Tapper at					\$
	Hrs. Labor at					\$
	Hrs. Labor at					\$
	Hrs. Compressor at					\$
	Compensation Ins.					\$
	Trucking					\$
	Builders Use of Water					\$
						\$
						\$
						\$
						\$
						\$
						\$

St. 12
Pt. B
Ave. No. B

Cherry
Name of Owner

Labor and Mat'l. Report SEP 6 - 1939 19



^{4"} Main Elev. of
Main at tap ^{6'}

Gate at ● ● Gate at

● Curb Box