

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4		\$ 1.23
1	Curb	Cock Valve T. S. & V.	3/4 in.		\$ 1.68
1	Service Box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway.			\$ 1.75
28	Ft.	3/4 in.		Copper Galv Iron Cast Iron	Pipe at 15 \$ 4.20
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	Couplings	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Leadite Joints	at			\$
	Hrs. Foreman	at			\$
5	Hrs. Chauffeur	at	6 2 1/2		\$ 3.13
	Hrs. Tapper	at			\$
22	Hrs. Labor	at	.45		\$ 9.90
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.				\$.31
	Trucking				\$ 1.00
	Builders Use of Water	Patch			\$ 5.00
	Tap by Person				\$
					\$
					\$
					\$
					\$ 28.20

49 - 1938

St.

Pl.

Ave. No. 33

Chester

Name of Owner

Jacobson

Labor and Mat'l. Report

Aug. 1

1938



● Curb Box

10" Main

Elev. of

Main at tap

5

Gate at ●

● Gate at

● Curb Box

Old tap disconnected.