

LABOR AND MATERIALS

1	Copper	} Connection	3/4"	\$	
1	Lead				
1	Curb	} Cock	3/4 in.	\$	
					} Valve
1	Service box	} Short 3 1/2 x 4 1/2		\$	
	Old returned				} Long 4 1/2 x 5 1/2
34	3/4	} Copper	} Pipe at	\$	
Ft.	in.				} G.I.
	Nipples	in. at	\$		
	Bushings	to in. at	\$		
	Red'g	} Coupl'gs	to in. at	\$	
	Inc'g				
	Union	in. at	\$		
	Meter	in. at	\$		
	Lead Joints	at	\$		
	Compound Joints	at	\$		
	Maintenance Foreman		\$		
	Hrs. Water Maint. Man-1	at	\$		
	Hrs. Water Maint. Man-2	at	\$		
	Hrs. Garage Foreman	at	\$		
	Hrs. Labor	at	\$		
	Hrs. Compressor	at	\$		
	Compensation Ins. at \$	per C	\$		
	Trucking		\$		
	Pav't Patch		\$		
	TAP BY GLESON		\$		
	CO. 5-16-60.		\$		
	O'head		\$		
			\$		

✓

St. Chester
Pl. 35
Ave. No. 35

Name of Owner Katherine V. Keese

Labor and Mat'l. Report May 16 1960

10" Main Elev. of Main at tap 5 1/2

Gate at ● ● Gate at

TAX ID # 302.16-19-8

● Curb Box

LSM-5C-2-8 56