

LABOR AND MATERIALS

1 Copper } Connection <sup>3/4</sup> \$ \_\_\_\_\_  
 Lead }  
 1 Curb } Cock } <sup>3/4</sup> in. \$ \_\_\_\_\_  
           } Valve }  
           } T.S. & V. }  
 1 Service box } { Short <sup>3 1/2</sup> x <sup>4 1/2</sup> }  
 Old returned } { Long 4 1/2 x 5 1/2 } \$ \_\_\_\_\_

9 Ft. <sup>3/4</sup> in. { Copper } Pipe at. \$ \_\_\_\_\_  
                   { C.I. }  
                   { C.P. }

Nipples \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Bushings \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Red'g }  
 Inc'g } Coupl'gs \_\_\_\_\_ to \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Union \_\_\_\_\_ in. at \$ \_\_\_\_\_  
 Meter \_\_\_\_\_ in. at \$ \_\_\_\_\_

Compound Joints at \$ \_\_\_\_\_  
 Maintenance Foreman \$ \_\_\_\_\_  
 Hrs. Water Maint. Man—1 at \$ \_\_\_\_\_  
 Hrs. Water Maint. Man—2 at \$ \_\_\_\_\_  
 Hrs. Garage Foreman \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Labor— \_\_\_\_\_ at \$ \_\_\_\_\_  
 Hrs. Compressor at \$ \_\_\_\_\_

Trucking \$ \_\_\_\_\_  
 Pav't Patch \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_  
 \_\_\_\_\_ \$ \_\_\_\_\_

St. PL  
 Ave. No. 36  
CHESTER

Name of Owner \_\_\_\_\_

Labor and Mat'l. Report

NOV 1934



32' 1/6" 24' 3"

● Curb Box

10" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box