

**Labor and Materials**

1	Copper } Connection	3/4	\$	2.60
1	Curb } Cock		\$	2.30
	Value } T.S. & V.		\$	
1	Service Box } Short 3 1/2 x 4 1/2		\$	1.40
	Old returned } Long 4 1/2 x 5 1/2		\$	
		Buff. or Rdway	\$	
14	Ft. 3/4 in. } Copper		\$	3.71
		Galv. Iron	\$	
		Cast Iron	\$	
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g } Couplings	to in. at	\$	
	Inc'g }		\$	
	Union	in. at	\$	
	Meter	in. at	\$	
	Lbs. Br. Stone	at	\$	
	Lbs. Sand	at	\$	
	Bags Cement	at	\$	
	Paving Brick } Mack	at	\$	
		Red	\$	
		Asphalt	\$	
	Lead Joints	at	\$	
	Leadite Joints	at	\$	
4	Hrs. Foreman	at	\$	2.50
1.4	Hrs. Common Labor	at	\$	5.69
	Hrs. Common Labor	at	\$	
	Hrs. Mason	at	\$	
	Hrs. Mason's Helper	at	\$	
	Hrs. Compressor	at	\$	
	Compensation Ins		\$	.22
	Trucking		\$	1.00
	Builders' Use of Water	Patch	\$	5.00

Total \$ 24.42

29-141 Labor and Material Report 8/25 19 29

16 Church St



6" Main Elev of Main at tap 5'

Gate at Curb Box Gate at

Get top shut off

RAZED