

Labor and Materials

Lead Connection	3/4"	\$
Curb Cock		\$
Service Box	{ Short 3 1/2 x 4 1/2	\$
Old returned	{ Long 4 1/2 x 6 1/2	\$
	Buffalo	
8 Ft.	in. G. I. Pipe at	\$
	Nipples in. at	\$
1	Bushings 1 to 1 1/2 in. at	\$
	Red'g Coup to in. at	\$
	Inc'g Coup to in. at	\$
	Union in. at	\$
	Meter in. at	\$
	Cu. Yds. Br. Stone at	\$
	Cu. Yds. Sand at	\$
	Bags Cement at	\$
	Paving Brick { Mack	} at \$
	Red	
	Asphalt	
4	Hrs. Foreman at	\$
5	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs. at	\$
	Hrs. at	\$
No	Builders' Use of Water	\$
	at	\$
Truck 100	at	\$
	at	\$
	at	\$
	Total	\$

Labor and Material Report

3/4 tap at 9 Church St

St Mary Church

26'2"

29'4" Curb Box

Pole #4066 N.Y.P. Sept 20-16

4' Main Elev. of Main at tap 4.11

Gate at ● Gate at ●

● Curb Box

This Place Razed. Shut off at curb