

Labor and Materials

Copper } Connection.....	$\frac{3}{4}$	\$ 2.70
Lead }		
Curb } Cock Valve }	$\frac{3}{4}$	\$ 2.39
} T. S. & V. }		
Service Box } Short $3\frac{1}{2} \times 4\frac{1}{2}$ }		\$ 1.45
Old returned } Long $4\frac{1}{2} \times 5\frac{1}{2}$ }		
} Buff. or Rdway }		
8 Ft. } in. } Copper } Pipe at.....	$\frac{3}{4}$	\$ 2.16
} } Galv. Iron }		
} } Cast Iron }		
Nipples.....	in. at.....	\$
Bushings.....	to..... in. at.....	\$
Red'g } Couplings.....	to..... in. at.....	\$
Inc'g }		
Union.....	in. at.....	\$
Meter.....	in. at.....	\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement at.....		\$
Paving Brick } Mack } at.....		\$
} Red }		
} Asphalt }		
Lead Joints at.....		\$
Leadite Joints at.....		\$
1 Hrs. Foreman at.....		\$ 6.3
1.7 Hrs Common Labor at.....		\$ 4.0
Hrs. Common Labor at.....		\$
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....		\$ 1.9
Trucking.....		\$ 1.1
Builders' Use of Water.....	Patch	\$ 5.1
Total		\$ 70.92

30-125

Labor and Material Report

29 19

19 Church St



6 Main

Elev of Main at tap 5.2

Gate at ●

● Gate at

● Curb Box

This Place
Razed
shut off at curb.