~~St.~~ ~~Pl.~~ COOLIDGE Ave. No. 40

Name of Owner

Labor and Mat'l. Report JUNE 6 1923

39'11" 29'6"

● Curb Box

6" Main Elev. of Main at tap 6'

Gate at ● ● Gate at

31' to main

1¼" GAL ● Curb Box

LSM—5C—6-1-67

LABOR AND MATERIALS

1 ~~Copper~~ Lead } Connection 1" $

1 Curb } ~~Cock~~ Valve ~~T.S. & V.~~ } 1¼" in. $

1 Service box { Short 3½ x 4½ / ~~Old returned~~ Long 4½ x 5½ } $

31 Ft. 1¼" in. { ~~Copper~~ G. I. ~~C. I.~~ } Pipe at $

Nipples in. at $

Bushings to in. at $

Red'g Inc'g } Coupl'gs to in. at $

Union in. at $

Meter in. at $

$

Compound Joints at $

Maintenance Foreman $

Hrs. Water Maint. Man—1 at $

Hrs. Water Maint. Man—2 at $

Hrs. Garage Foreman at $

Hrs. Labor— at $

Hrs. Compressor at $

$

Trucking $

Pav't Patch $

$

$

$

$

$