

St. CLAY DGE
 Pl. 57
 Ave. No. 57

Name of Owner
DECKER

Labor and Mat'l. Report AUG 15 1928



27'10" 26'9"
 ● Curb Box

6" Main Elev. of Main at tap 4 1/2'

Gate at ● ● Gate at

TAX ID # 302.15-10-18

● Curb Box

REVERSE CURB STOP
 IS ON IN "OFF" POSITION

LSM-SC-6-1-67

OLD TAP DISCONNECTED

LABOR AND MATERIALS

1	Copper Lead	Connection	<u>3/4</u>	\$	
1	Curb	Cock Valve T. S. & V.	<u>3/4</u> in.	\$	
1	Service box Old returned	Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$		\$	
43	Ft.	<u>3/4</u> in. { Copper C.T. C.T. }	Pipe at	\$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g } Inc'g }	Coupl'gs	to in. at	\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man-1	at		\$	
	Hrs. Water Maint. Man-2	at		\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Trucking			\$	
	Pav't Patch			\$	
				\$	
				\$	
				\$	
				\$	