

LABOR AND MATERIALS

1	Copper	} Connection	_____	\$
	Lead		_____	\$
1	Curb	} Cock Valve T. S. & V.	_____ in.	\$
			_____	\$
			_____	\$
1	Service box	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2	_____	\$
	Old returned		_____	\$
13	Ft. / in.	} Copper G. I. C.P.	_____ Pipe at	\$
			_____	\$
	Nipples	_____ in. at	\$	
	Bushings	_____ to _____ in. at	\$	
	Red'g } Inc'g }	Coupl'gs. _____ to _____ in. at	\$	
	Union	_____ in. at	\$	
	Meter	_____ in. at	\$	
	Compound Joints	_____ at	\$	
	Maintenance Foreman	_____ at	\$	
	Hrs. Water Maint. Man—1	_____ at	\$	
	Hrs. Water Maint. Man—2	_____ at	\$	
	Hrs. Garage Foreman	_____ at	\$	
	Hrs. Labor—	_____ at	\$	
	Hrs. Compressor	_____ at	\$	
	Trucking	_____	\$	
	Pav't Patch	_____	\$	
		_____	\$	
		_____	\$	
		_____	\$	
		_____	\$	
		_____	\$	

St. _____
~~Pr.~~ _____
 Ave. No. 324B

COOPER
 Name of Owner _____
 TAX ID # 303.17-3-3

Labor and Mat'l. Report JUNE 4 1924



● Curb Box

_____ Main _____ Elev. of Main at tap _____
 Gate at ● _____ Gate at ● _____

● Curb Box