Labor and Materials

1 1/4	Lead Connection	$
1	Curb Cock 1 1/4 Valve	$
1	Service Box Old returned { Short 3½ x 4½ / Long 4½ x 5½ / Buffalo } + Hood	$
5	Ft. 1 1/2 in. G. I. Pipe at	$
	Nipples in. at	$
	Bushings to in. at	$
	Red'g Coup to in. at	$
	Inc'g Coup to in. at	$
	Union in. at	$
	Meter in. at	$
	Cu. Yds. Br. Stone at	$
	Cu. Yds. Sand at	$
	Bags Cement at	$
	Paving Brick { Mack / Red / Asphalt } at	$
3	Hrs. Foreman at	$
	Hrs. Common Labor at	$
	Hrs. Mason at	$
	Hrs. at	$
	Hrs. at	$
Quo	Builders' Use of Water	$
	at	$
	at	$
	at	$
	at	$
	Total	$ 14.46

Labor and Material Report June 21 1954

1 1/2 Tap Kendrick + Brown

#45

Curb Box

4" Main

Elev. of Main at tap 6'

Gate at

Gate at

Aug 14-57

Curb Box

This Tap is Disconnected at Main new 2" Galv Renewal Tap.