

LABOR AND MATERIALS

1 Copper	{ Connection	3/4		\$ 2.29
1 Lead				
1 Curb	{ Cock Valve	3/4	in.	\$ 2.70
	{ T.S. & V.			
1 Service box	{ Short 3 1/2 x 4 1/2			
Old returned	{ Long 4 1/2 x 5 1/2			\$ 4.25
	{ Buff or Rdway			
11 Ft. 3/4 in.	{ Copper		Pipe at 35	\$ 3.85
	{ G.I.			
	{ C.I.			
Nipples	in. at			\$
Bushings	to in. at			\$
Red'g Inc'g	{ Coupl'gs to in. at			\$
Union	in. at			\$
Meter	in. at			\$
Lead Joints at				\$
Compound Joints at				\$
Hrs. Water Maint. Man-1 at				\$
4 Hrs. Water Maint. Man-2 at		1.02		\$ 4.08
1 Hrs. Labor—	at	91		\$ 91
Hrs. Labor—	at			\$
Hrs. Compressor at				\$
Compensation Ins. at \$	per C.			\$ 11
Trucking				\$ 1.00
Pav't Patch				\$
<i>Tap by Muz... ..</i>				
O'head				\$
				\$ 19.19

St.
 Ave. No. 124

Cooper

Name of Owner Nelson

Labor and Mat'l. Report June 23 1950

6" Main
Elev. of Main at tap 9'

Gate at ● Gate at ●

TAX ID # 303.13-3-5

● Curb Box

LSM-5C 10-21-49