

### LABOR AND MATERIALS

Copper	} Connection		\$
Lead			
Curb	} Clock Valve T. S. & V. }	..... in.	\$
Service box		} Short 3 1/2 X 4 1/2 } Long 4 1/2 X 5 1/2 } Buff or Rdway }	
Old returned			
Ft. .... in.	Copper } Galv. Iron } Cast Iron }		Pipe at
Nipples	..... in. at		\$
Bushings	..... to .....	in. at	\$
Red'g } Inc'g }	} Couplings	..... to .....	\$
Union		..... in. at	\$
Meter	..... in. at		\$
Lead Joints	at		\$
Compound Joints	at		\$
Hrs. Foreman	at		\$
Hrs. Chauffeur	at		\$
Hrs. Tapper	at		\$
Hrs. Labor	at		\$
Hrs. Labor	at		\$
Hrs. Compressor	at		\$
Compensation Ins.			\$
Trucking			\$
Builders Use of Water			\$
			\$
			\$
			\$
			\$
			\$

St.  
~~Pl.~~  
Ave. No. 19

19 Cooper

Name of Owner  
McMullen & Levens Co

Labor and Mat'l. Report Oct 17 1947

Shut off at Main  
Oct 17-47  
Pykalsinski

● Curb Box

Main Elev. of Main at tap.....

Gate at ● ● Gate at

TAX ID # 303.17-13-10

● Curb Box

leaker in service pipe

This Place taken from  
from McMullen & Levens  
Factory

### LABOR AND MATERIALS

Copper	}	Connection	-----	\$	
Lead					
Curb	{	Cock Valve	----- in. -----	\$	
		T. S. & V.			
Service Box	{	Short 3 1/2 x 4 1/2	-----	\$	
Old returned		Long 4 1/2 x 5 1/2			
		Buff. or Rdway			
Ft. -----	in. -----	{	Pipe at -----	\$	
					Copper
					Galv Iron
		Cast Iron			
Nipples	in. at -----			\$	
Bushings	----- to -----	in. at -----		\$	
Red'g	{	Couplings	----- to -----	\$	
Inc'g					in. at -----
Union	in. at -----			\$	
Meter	in. at -----			\$	
Lead Joints	at -----			\$	
Leadite Joints	at -----			\$	
Hrs. Foreman	at -----			\$	
Hrs. Chauffeur	at -----			\$	
Hrs. Tapper	at -----			\$	
Hrs. Labor	at -----			\$	
Hrs. Labor	at -----			\$	
Hrs. Compressor	at -----			\$	
Compensation Ins.	-----			\$	
Trucking	-----			\$	
Builders Use of Water	-----			\$	
				\$	
				\$	
				\$	
				\$	
				\$	


St. 19  
 Pt. 9  
 Ave. No.

*Cooper*

**Name of Owner** \_\_\_\_\_

---

**Labor and Mat'l. Report** 19

19  
*House Razed*  


● Curb Box

---

Main	Elev. of Main at tap
Gate at ●	● Gate at

---

● Curb Box

*This Place Shut off at  
Main take water from  
with the yellow service  
Oct 17-97  
by Warsaw (Leak in Service pipe)*