

LABOR AND MATERIALS

1	Copper Lead	} Connection	3/4	\$
1	Curb			
1	Service box Old returned	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2		\$
8	Ft. 3/4 in.			
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g } Inc'g }	Coupl'gs	to in. at	\$
	Union	in. at	\$	
	Meter	in. at	\$	
			\$	
	Compound Joints	at	\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man	1 at	\$	
	Hrs. Water Maint. Man	2 at	\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor	at	\$	
			\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	

CORTLAND St. Ave. No. 7
 Name of Owner

Labor and Mat'l. Report AUG 7 19 29



● Curb Box

6" Main Elev. of Main at tap 4 1/2'

Gate at ● Gate at

8' to main

● Curb Box

OLD TAP SHUT OFF AT MAIN

Tax Map #309.7-7-14