

LABOR AND MATERIALS

1	Copper	} Connection	3/4	\$	
	Lead				
1	Curb	} Cock Valve T.S. & V. }	3/4 in.	\$	
1	Service box	} Short 3 1/2 x 4 1/2 } Long 4 1/2 x 5 1/2 }		\$	
	Old returned				
20	Ft. 3/4 in.	} Copper } G.I. } C.I. }	} Pipe at	\$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g } Inc'g }	} Coupl'gs. to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man-1	at		\$	
	Hrs. Water Maint. Man-2	at		\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
	Trucking			\$	
	Pav't Patch			\$	
				\$	
				\$	
				\$	
				\$	

St. CORTLAND Pt. Ave. No. 10

Name of Owner \_\_\_\_\_

Labor and Mat'l. Report MAY 18 1926



● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

20' to main

● Curb Box

NEW TAP

NEW HOUSE