

LABOR AND MATERIALS

Copper	} Connection		\$	
Lead				
Curb	} T. S. & V. }	in.	\$	
				Cock
				Valve
Service box	} Short 3½ x 4½ }		\$	
Old returned				Long 4½ x 5½ }
13 Ft. ^{3/4} in.	} Copper G.I. G.I. }	} Pipe at	\$	
Nipples				in. at
Bushings				to in. at
Red'g	} Coupl'gs	to in. at	\$	
Inc'g				
Union	in. at	\$		
Meter	in. at	\$		
Compound Joints	at	\$		
Maintenance Foreman		\$		
Hrs. Water Maint. Man—1	at	\$		
Hrs. Water Maint. Man—2	at	\$		
Hrs. Garage Foreman	at	\$		
Hrs. Labor—	at	\$		
Hrs. Compressor	at	\$		
Trucking		\$		
Pav't Patch		\$		
		\$		
		\$		
		\$		
		\$		
		\$		

CRANDALL St. ~~Pr.~~ Ave. No. 26

Name of Owner

Labor and Mat'l. Report Oct, 1989



● Curb Box

10 Main Elev. of Main at tap 4 1/2'

Gate at ● Gate at

● Curb Box