

LABOR AND MATERIALS

~~3/4~~ <sup>Copper</sup> } Connection 3/4 10/7/06 \$  
~~3/4~~ <sup>Copper</sup> }  
 Curb } Cock } 1" in. \$  
 } Valve }  
 } T.S. & V. }  
~~3/4~~ Service box { Short 3 1/2 x 4 1/2 }  
 Old returned { Long 4 1/2 x 5 1/2 }  
~~15~~ Ft. 3/4 in. { Copper } (Copper) \$  
 } G. I. }  
 } C.P. } Pipe at \$  
 Nipples in. at \$  
~~2~~ Bushings ~~2~~ to ~~2~~ in. at \$  
 Red'g }  
 Inc'g } Coupl'gs to in. at \$  
 Union in. at \$  
 Meter in. at \$  
 Compound Joints at \$  
 Maintenance Foreman Tommy + Curt P  
 Hrs. Water Maint. Man—1 at \$  
 Hrs. Water Maint. Man—2 at \$  
 Hrs. Garage Foreman at \$  
 Hrs. Labor— at \$  
 Hrs. Compressor at \$  
 Trucking \$  
 Pav't Patch \$  
 \$  
 \$  
 \$  
 \$  
 \$  
 \$

CRANDALL

St. ~~11~~ No. 28

Name of Owner  
TAX ID # 309.27-2-3

Labor and Mat'l. Report (new) 10/7/06  
line SEPT 3 1924



30'-2" 22'-10"

● Curb Box

10" Main

Elev. of Main at tap 6'

Gate at ●

● Gate at

● Curb Box