

Labor and Material Report

19

no 46 Crandall St



Curb Box

Main Elev. of Main at tap
Gate at Gate at

Curb Box

Probably
sized

Labor and Materials

Copper } Connection		\$ 3.20
Lead }		
Curb { Cock		\$ 1.00
Valve }		
T. S. & V. }	in.	
Service Box { Short 3 1/2 x 4 1/2		\$ 1.30
Old returned { Long 4 1/2 x 5 1/2		
	Buff. or Rdway	
Pt. 3/4 in. { Copper		\$ 5.50
	Galv. Iron } Pipe at	
	Cast Iron }	
Nipples	in. at	\$
Bushings	to in. at	\$
Red'g } Couplings	to in. at	\$ 1.15
Inc'g }		
Union	in. at	\$
Meter	in. at	\$
Lbs. Br. Stone	at	\$
Lbs. Sand	at	\$
Bags Cement	at	\$
Paving Brick { Mack		\$
	Red } at	
	Asphalt }	
Lead Joints	at	\$
Leadite Joints	at	\$
2 Hrs. Foreman	at	\$ 1.00
20 Hrs. Common Labor	at	\$ 8.12
Hrs. Common Labor	at	\$
Hrs. Mason	at	\$
Hrs. Mason's Helper	at	\$
Hrs. Compressor	at	\$
Compensation Ins.		\$ 24
Trucking		\$ 1.50
Builders' Use of Water		\$

Total \$ 21.57