

LABOR AND MATERIALS

1	Copper Lead	} Connection $\frac{3}{4}$ "		\$
1	Curb		} Cock Valve T.S.&V. } 1" in.	
1	Service box Old returned	} Short $3\frac{1}{2}$ x $4\frac{1}{2}$ } Long $4\frac{1}{2}$ x $5\frac{1}{2}$ }		
10	Ft. 1" in.		} Copper G.I. } Pipe at	
	Nipples	in. at		
1	Bushings	to $\frac{1}{2}$ " in. at		\$
	Red'g Inc'g } Coupl'gs	to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man	1 at		\$
	Hrs. Water Maint. Man	2 at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$
				\$

CRANDALL

St. ~~St.~~ Ave. No. 65

Name of Owner

Labor and Mat'l. Report

SEPT 16 1924



31'4" 28'

● Curb Box

10" Main

Elev. of Main at tap 4'

Gate at ●

● Gate at

● Curb Box