

LABOR AND MATERIALS

1	Copper	} Connection $\frac{3}{4}$	\$	
	Lead			
1	Curb	} Cock Valve } 1 in.	\$	
			} T.S. & V. }	
1	Service box			{ Short $3\frac{1}{2}$ x $4\frac{1}{2}$
	Old returned	{ Long $4\frac{1}{2}$ x $5\frac{1}{2}$	\$	
17	Ft.	} Copper } Pipe at	\$	
	1 in.		} G.I. }	
				} G.P. }
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g	} Coupl'gs. to in. at	\$	
	Inc'g			
	Union	in. at	\$	
	Meter	in. at	\$	
			\$	
	Compound Joints	at	\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man-1	at	\$	
	Hrs. Water Maint. Man-2	at	\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor	at	\$	
			\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	
			\$	

St. ~~St.~~
CRANDALL
~~Ave.~~ No. 66

Name of Owner _____

Labor and Mat'l. Report JULY 29 1924



27'-8" 21'-10"

● Curb Box

10" Main Elev. of Main at tap 4'

Gate at ● ● Gate at

● Curb Box

OLD TAP TO BE DUG UP