

*Bill rendered at*

**Labor and Materials**

1	Copper } Connection.....	3/4	\$	320
	Lead			
1	Curb } Cock			
		Valve		
		T.S. & V.		
		in.....	\$	1.50
1	Service Box } Short 3 1/2 x 4 1/2			
	Old returned } Long 4 1/2 x 5 1/2			
		Buff. or Rdway	\$	1.30
13	Ft. 3/4 in. } Copper			
		Galv. Iron		
		Cast Iron		
		} Pipe at.....	\$	286
	Nipples.....	in. at.....	\$	
	Bushings.....	to..... in. at.....	\$	
	Red'g } Couplings.....	to..... in. at.....	\$	
	Inc'g			
	Union.....	in. at.....	\$	
	Meter.....	in. at.....	\$	
	Lbs. Br. Stone at.....		\$	
	Lbs. Sand at.....		\$	
	Bags Cement at.....		\$	
	Paving Brick } Mack			
		Red		
		Asphalt		
		} at.....	\$	
	Lead Joints at.....		\$	
	Leadite Joints at.....		\$	
	Hrs. Foreman at.....		\$	
	Hrs. Common Labor at.....		\$	
	Hrs. Common Labor at.....		\$	
	Hrs. Mason at.....		\$	
	Hrs. Mason's Helper at.....		\$	
	Hrs. Compressor at.....		\$	
	Compensation Ins.....		\$	
	Trucking.....		\$	
	Builders' Use of Water.....		\$	

Total \$.....

**Labor and Material Report**

*June 90* 19

*no 71 Crandell st*  
*no measurement*

● Curb Box

10" Main

Elev. of Main at tap *5'*

Gate at ●

● Gate at

● Curb Box

*vacant lots*

REAR OF 38 GROVE