

LABOR AND MATERIALS

1	Copper	} Connection		\$	
	Lead				
1	Curb	} Water T.S. & V.	} $\frac{3}{4}$ in.	\$	
1	Service box	} Short $3\frac{1}{2} \times 4\frac{1}{2}$	}	\$	
	Old returned				Long $4\frac{1}{2} \times 5\frac{1}{2}$
22	Ft. $\frac{3}{4}$ in.	} Copper C.P. C.P.	} Pipe at	\$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
1	Redg Inc'g	} Coupl'gs BRASS	} to in. at	\$	
	Union	in. at		\$	
	Meter	in. at		\$	
				\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man-1	at		\$	
	Hrs. Water Maint. Man-2	at		\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
				\$	
	Trucking			\$	
	Pav't Patch			\$	
				\$	
				\$	
				\$	
				\$	

St. CRANDALL
~~St.~~
 Ave. No. 74

Name of Owner _____

Labor and Mat'l. Report APR. 21 1926



36'3" 20'2"

● Curb Box

10" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box