

LABOR AND MATERIALS

1	Copper	} Connection $\frac{3}{4}$		\$
1	Lead			\$
1	Curb	} Cock Valve T.S. & V. } $\frac{3}{4}$ in.		\$
1	Service box Old returned		} Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ }	
9	Ft. $\frac{3}{4}$ in.	} Copper C.I. C.I.		Pipe at
	Nipples		in. at	\$
	Bushings	to in. at	\$	
	Red'g } Inc'g }	Coupl'gs to in. at	\$	
	Union	in. at	\$	
	Meter	in. at	\$	
	Compound Joints	at	\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man-1	at	\$	
	Hrs. Water Maint. Man-2	at	\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor-	at	\$	
	Hrs. Compressor	at	\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	
			\$	

CRANDALL

St.

~~St.~~

No. 107

Name of Owner

Labor and Mat'l. Report

JUNE 9 1927



32'2" 29'8"

● Curb Box

10" Main

Elev. of

Main at tap

5'

Gate at ●

● Gate at

● Curb Box

ALEX HIRSCH