

LABOR AND MATERIALS

1 Copper } Connection $\frac{3}{4}$		\$	
Lead			
1 Curb } Cock	$\frac{3}{4}$ in.	\$	
Valve			
F.S. & V.			
1 Service Box	} Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buffer Rdway	\$	
Old returned			
8 Ft. $\frac{3}{4}$ in.			
	} Copper Galvanized Cast Iron	Pipe at	\$
Nipples	in. at	\$	
Bushings	to in. at	\$	
Red'g } Couplings	to in. at	\$	
Inc'g			
Union	in. at	\$	
Meter	in. at	\$	
Lead Joints	at	\$	
Leadite Joints	at	\$	
Hrs. Foreman	at	\$	
Hrs. Chauffeur	at	\$	
Hrs. Tapper	at	\$	
Hrs. Labor	at	\$	
Hrs. Labor	at	\$	
Hrs. Compressor	at	\$	
Compensation Ins.		\$	
Trucking		\$	
Builders Use of Water		\$	
		\$	
		\$	
		\$	
		\$	
		\$	
		\$	

St. Crandall
 Pt. 125
 Ave. No. 125

Name of Owner _____

TAP MADE JUNE 9, 1927

Labor and Mat'l. Report **AUG 24 1939** 19

122

124.6

67'-0"

79'-0"

● Curb Box

10" Main

Elev. of Main at tap

● Gate at ● Gate at

● Curb Box

Lot TAP