1 5 3 - 1940

St. 10
~~Pl.~~
Culvert Ave. No. 6

Name of Owner

Young

Labor and Mat'l. Report Oct 15 1940

4" gal. Main

Elev. of Main at tap 5½'

Gate at ● ● Gate at

TAX ID # 303.17-18-1

● Curb Box

tm

LABOR AND MATERIALS

1 Copper ~~Lead~~ Connection $ 1.31

1 Curb { Cock ~~Valve~~ ~~T. S. & V.~~ } ¾ in. $ 1.75

1 Service Box ~~Old returned~~ { Short 3½x4½ ~~Long 4½x5½~~ ~~Buff. or Rdway~~ } $ 1.60

16 Ft. ¾ in. { Copper ~~Galv Iron~~ ~~Cast Iron~~ } Pipe at 18 $ 2.88

Nipples ____ in. at ____ $ ____

Bushings ____ to ____ in. at ____ $ ____

Red'g Inc'g } Couplings ____ to ____ in. at ____ $ ____

Union ____ in. at ____ $ ____

Meter ____ in. at ____ $ ____

Lead Joints at ____ $ ____

Leadite Joints at ____ $ ____

Hrs. Foreman at ____ $ ____

3 Hrs. Chauffeur at 62½ $ 1.88

5½ Hrs. Tapper at ____ $ 3.44

15 Hrs. Labor at 45 $ 6.75

Hrs. Labor at ____ $ ____

Hrs. Compressor at ____ $ ____

Compensation Ins. ____ $ .37

Trucking ____ $ 1.—

Builders Use of Water ____ $ ____

tap by Hassel ____ $ ____

____ $ ____

____ $ ____

____ $ ____

$ 20.98