

LABOR AND MATERIALS

1	Copper Lead	Connection			\$ 123
1	Curb	Cock Valve T. S. & V.	3/4 in.		\$ 168
1	Service Box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway			\$ 175
9	Ft.	3/4 in.		Copper Galv Iron Cast Iron	Pipe at 15 \$ 135
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	Couplings	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Leadite Joints	at			\$
	Hrs. Foreman	at			\$
2	Hrs. Chauffeur	at	6 1/2		\$ 125
1	Hrs. Tapper	at	"		\$.63
8	Hrs. Labor	at	45		\$ 3.60
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.				\$.17
	Trucking				\$ 1.00
	Builders Use of Water	patches			\$ -
	Tap by Miller				\$
					\$
					\$
					\$
					\$
					\$ 17.66

145-38

St. _____
Pl. _____
Ave. No. 44

Name of Owner
Peck

Labor and Mat'l. Report Oct 29 1938

Curb Box

6 Main Elev. of Main at tap 5

Gate at ● ● Gate at

TAX ID # 302.19-3-6

● Curb Box

New House