

LABOR AND MATERIALS

1	Copper Lead	Connection	$\frac{3}{4}$	\$
1	Curb	Cock Valve	$\frac{3}{4}$ in.	\$
1	Service box	Short	$3\frac{1}{2} \times 4\frac{1}{2}$	\$
Old returned	Long	$4\frac{1}{2} \times 5\frac{1}{2}$		
25	Ft.	Copper Pipe	$\frac{3}{4}$ in.	\$
	Nipples	in.	at	\$
	Bushings	to	in. at	\$
	Red'g Inc'g	Coupl'gs	to in. at	\$
	Union	in.	at	\$
	Meter	in.	at	\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$
				\$
				\$

~~St~~  
~~Pr~~  
CUNNINGHAM Ave. No. 13

Name of Owner

Labor and Mat'l. Report

NOV. 11 1931



● Curb Box

6" Main

Elev. of Main at tap 44'

Gate at ●

● Gate at

● Curb Box