

LABOR AND MATERIALS

1	Copper Lead	{ Connection	-----	\$	
1	Curb	{ Cock Valve T. S. & V.	----- in.	\$	
1	Service Box	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway	-----	\$	
	Old returned				
23	Ft. 1		{ Copper Galv Iron Cast Iron	-----	\$
34	in. 1/2				
	Nipples	----- in.	at	\$	
	Bushings	----- to -----	in. at	\$	
	Red'g Inc'g	} Couplings	----- to -----	in. at	\$
	Union	----- in.	at	\$	
	Meter	----- in.	at	\$	
	Lead Joints	-----		\$	
	Leadite Joints	-----		\$	
	Hrs. Foreman	-----		\$	
	Hrs. Chauffeur	-----		\$	
	Hrs. Tapper	-----		\$	
	Hrs. Labor	-----		\$	
	Hrs. Labor	-----		\$	
	Hrs. Compressor	-----		\$	
	Compensation Ins.	-----		\$	
	Trucking	-----		\$	
	Builders Use of Water	-----		\$	
		-----		\$	
		-----		\$	
		-----		\$	
		-----		\$	
		-----		\$	
		-----		\$	

Str 17
 FF
 Ave. No. 11

Cunningham

Name of Owner
TAP MADE DEC. 12 1924

Labor and Mat'l. Report AUG. 22 1939

● Curb Box

6" Main
Elev. of Main at tap 4'

Gate at ●
● Gate at

● Curb Box