

LABOR AND MATERIALS

1	Copper Lead	Connection	$\frac{3}{4}$ "	\$ 135
1	Curb	Cock Valve	$\frac{3}{4}$ " in.	\$ 180
1	Service box	Short $3\frac{1}{2}$ x $4\frac{1}{2}$	} same	\$
26'	Old returned	Long $4\frac{1}{2}$ x $5\frac{1}{2}$		
		Buff or Rdway		
23'	$\frac{3}{4}$ " in.	Copper Pipe at	lead	\$ 414
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
9	Hrs. Water Maint. Man-1	at	$68\frac{3}{4}$	\$ 619.00
1	Hrs. Water Maint. Man-2	at	"	\$ 69.00
	Hrs. Garage Foreman	at		\$
7	Hrs. Labor	at	55	\$ 385.00
	Hrs. Compressor	at		\$
	Compensation Ins. at	\$ 2.213 per C		\$ 25
	Trucking			\$ 100
	Pav't Patch			\$ 585
	Tap by Miller			\$
	7-15-59			\$
	O'head			\$
	Pipe renewed by			\$ 2512
	Gifford & Co			
	7-15-59			

✓ 4-43

St. _____
Pl. _____
Ave. No. 5

Darwin

Name of Owner
Mrs. Jeremiah Coyer.

Labor and Mat'l. Report April 12 1943

30' 6" 18" Curb Box

4" Main Elev. of Main at tap 5'

Gate at • Gate at •

• Curb Box

Renewed Pipe
with Copper,
7-15-59,

LSM-5C-2-5 56